

Summary of Facility Information in the County of Beaverhead

Owner Name and Address: Dell Center LLC PO Box 240064 Dell MT 59724 Phone: (406) 276-3332

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0101523	Dell Center LLC	24 Main St	Dell	59724	(406) 276-3332

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
4 / 04 Currently in Use	5045	10/6/2005 00 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently in Use	5046	10/6/2005 00 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
6 / 06 Currently in Use	5047	10/6/2005 00 / No	Diesel 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently in Use	5048	10/6/2005 00 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Beaverhead

Owner Name and Address: Canyon Ranch PO Box 240084 Dell MT 59724 Phone: (406) 276-3369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0109843	Dell Airport Canyon Ranch		Dell	59724	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
1 / 01 Currently in Use	516	6/13/1989 17 / No	Other 10,000	STI-P3 Double-Walled	No Piping None	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Beaverhead

Owner Name and Address: The Mini Inc 410 N Montana St Dillon MT 59725 Phone: (406) 683-6168

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0101215	The Mini Inc	410 N Montana St	Dillon	59725	(406) 683-6168

TankID/Alt TankID	Tag	Installed	Product	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																								
Status	Number	Age/AST	Capacity	Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/CP																								
4 / 04	3088	5/6/1998	Gasoline	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
Currently In Use		08 / No	12,000	None	Double-Walled			Yes Yes Yes																								
5 / 05	3089	5/6/1998	Gasoline	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
Currently In Use		08 / No	6,000	None	Double-Walled			Yes Yes Yes																								
6 / 06	3090	5/6/1998	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L			Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B	D	E	F	<input checked="" type="radio"/>	H	I	J	K	L																							
Currently In Use		08 / No	5,000	None	Double-Walled			Yes Yes Yes																								

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Beaverhead

Owner Name and Address: Tim Dietrich 636 S Atlantic St Dillon MT 59725 Phone: (406) 683-0070

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0105401	Dietrichs College Exxon UST	636 S Atlantic St	Dillon	59725	

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
1 / 05 Temporarily Out of Use	3227	7/1/1994 12 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I C K L</div> </div>	Yes Yes Yes Yes
2 / 04 Temporarily Out of Use	3226	7/1/1994 12 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I C K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Beaverhead

Owner Name and Address: Beaverhead County 2 S Pacific St Dillon MT 59725 Phone: (406) 683-5245

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0105668	County Courthouse	2 S Pacific St	Dillon	59725	(406) 683-2642

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
2 / 02 Currently in Use	421	2/1/1993 13 / No	Gasoline 2,000	STI-P3 Double-Walled	Galvanized Steel Cathodically Protected	Safe Suction	<div> <input checked="" type="radio"/>A <input checked="" type="radio"/>C <input checked="" type="radio"/>E <input checked="" type="radio"/>F <input checked="" type="radio"/>G <input checked="" type="radio"/>H <input checked="" type="radio"/>I <input checked="" type="radio"/>J <input checked="" type="radio"/>K <input checked="" type="radio"/>L </div>	<div> <input type="radio"/>B <input type="radio"/>D <input type="radio"/>E <input type="radio"/>F <input type="radio"/>G <input type="radio"/>H <input type="radio"/>I <input type="radio"/>J <input type="radio"/>K <input checked="" type="radio"/>L </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Beaverhead

Owner Name and Address: Hi Noon Petroleum PO Box 7578 Missoula MT 59807 Phone: (406) 532-0384

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0105780	Kwik Stop Dillon	536 S Atlantic St	Dillon	59725	(406) 683-5900

TankID/Alt TankID	Tag Number	Installed	Product	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																																																
Status		Age/AST	Capacity	Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/CP																																																
1 / 01	1298	4/25/1976	Gasoline	Cathodically Protected Steel	Flexible Plastic	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="12"></td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td colspan="2">E</td><td colspan="2">F</td><td colspan="2"><input checked="" type="radio"/></td><td colspan="2">H</td></tr><tr><td colspan="2"></td><td colspan="2"></td><td colspan="2"></td><td colspan="2"></td><td colspan="2"></td><td colspan="2"></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L													B		D		E		F		<input checked="" type="radio"/>		H														Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																																													
B		D		E		F		<input checked="" type="radio"/>		H																																														
Temporarily Out of Use		30 / No	12,000	Lined Interior/Impressed Curr	Double-Walled		<table><tr><td colspan="12"></td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td colspan="2">E</td><td colspan="2">F</td><td colspan="2"><input checked="" type="radio"/></td><td colspan="2">H</td></tr><tr><td colspan="2"></td><td colspan="2"></td><td colspan="2"></td><td colspan="2"></td><td colspan="2"></td><td colspan="2"></td></tr></table>													B		D		E		F		<input checked="" type="radio"/>		H														Yes Yes Yes												
B		D		E		F		<input checked="" type="radio"/>		H																																														
2 / 02	1299	4/25/1976	Gasoline	Cathodically Protected Steel	Flexible Plastic	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="12"></td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td colspan="2">E</td><td colspan="2">F</td><td colspan="2"><input checked="" type="radio"/></td><td colspan="2">H</td></tr><tr><td colspan="2"></td><td colspan="2"></td><td colspan="2"></td><td colspan="2"></td><td colspan="2"></td><td colspan="2"></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L													B		D		E		F		<input checked="" type="radio"/>		H														Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																																													
B		D		E		F		<input checked="" type="radio"/>		H																																														
Temporarily Out of Use		30 / No	6,000	Lined Interior/Impressed Curr	Double-Walled		<table><tr><td colspan="12"></td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td colspan="2">E</td><td colspan="2">F</td><td colspan="2"><input checked="" type="radio"/></td><td colspan="2">H</td></tr><tr><td colspan="2"></td><td colspan="2"></td><td colspan="2"></td><td colspan="2"></td><td colspan="2"></td><td colspan="2"></td></tr></table>													B		D		E		F		<input checked="" type="radio"/>		H														Yes Yes Yes												
B		D		E		F		<input checked="" type="radio"/>		H																																														

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Beaverhead

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0108695	Town Pump Inc Dillon 1	101 E Helena St	Dillon	59725	

TankID/Alt TankID	Tag Number	Installed	Product	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/CP																								
1 / 01 Currently in Use	4794	4/14/1961 45 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
4 / 04 Currently in Use	4795	1/1/1986 20 / No	Gasoline 10,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
5 / 05 Currently in Use	4796	1/1/1986 20 / No	Gasoline 12,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Beaverhead

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0108696	Town Pump Inc Dillon 2	635 N Montana St	Dillon	59725	

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP																								
1 / 10 Currently in Use	2375	9/10/1990 15 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
2 / 11 Currently in Use	2376	9/10/1990 15 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
4 / 07 Currently in Use	2372	9/10/1990 15 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
5 / 08 Currently in Use	2373	9/10/1990 15 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
6 / 09 Currently in Use	2374	9/10/1990 15 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
7 / 13 Currently In Use	4541	5/1/1999 07 / No	Diesel 6,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
8 / 14 Currently In Use	4356	8/20/2001 04 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
9 / 15 Currently In Use	4357	8/20/2001 04 / No	Diesel 5,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Beaverhead

Owner Name and Address: Rocky Mountain Supply Inc PO Box 129 Belgrade MT 59714 Phone: (406) 388-4008

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0110034	Rocky Mountain Supply Inc Dillon	700 N Montana St	Dillon	59725	(406) 683-2308

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
1 / 01 Currently In Use	3900	1/12/1981 25 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently In Use	3901	1/12/1981 25 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently In Use	3902	1/12/1981 25 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / 04 Currently In Use	3903	1/12/1981 25 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / 05 Currently In Use	3904	1/12/1981 25 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
9 / 09 Currently In Use	3905	12/1/1998 07 / No	Gasoline 12,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
10 / 10 Currently In Use	3906	12/1/1998 07 / No	Gasoline 4,100	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes
11 / 11 Currently In Use	3907	12/1/1998 07 / No	Gasoline 7,900	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<div> <div>A B C D E F <input checked="" type="radio"/> H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Beaverhead

Owner Name and Address: David Walker 6615 North 15 East Idaho Falls ID 83402 Phone: (208) 522-3331

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0113101	Big Sky Truck Stop Dillon	4055 Rebich Ln	Dillon	59725	(406) 683-2666

TankID/Alt TankID Status	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/CP
1 / 01 Temporarily Out of Use	4634	7/1/1993 13 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A●●●D●E●F●G●H●I●J●K●L</div> <div>●●●E●F●G●H●I●J●K●L</div> </div>	Yes Yes Yes Yes
2 / 02 Temporarily Out of Use	4635	7/1/1993 13 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A●●●D●E●F●G●H●I●J●K●L</div> <div>●●●E●F●G●H●I●J●K●L</div> </div>	Yes Yes Yes Yes
3 / 03 Temporarily Out of Use	4636	7/1/1993 13 / No	Diesel 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A●●●D●E●F●G●H●I●J●K●L</div> <div>●●●E●F●G●H●I●J●K●L</div> </div>	Yes Yes Yes Yes
4 / 04 Temporarily Out of Use	4637	7/1/1993 13 / No	Diesel 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A●●●●D●E●F●G●H●I●J●K●L</div> <div>●●●E●F●G●H●I●J●K●L</div> </div>	Yes Yes Yes Yes
5 / 05 Temporarily Out of Use	4638	7/1/1993 13 / No	Diesel 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A●●●●D●E●F●G●H●I●J●K●L</div> <div>●●●E●F●G●H●I●J●K●L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Beaverhead

Owner Name and Address: Beaverhead County 2 S Pacific St Dillon MT 59725 Phone: (406) 683-5245

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613894	Dillon Airport	2400 Airport Road	Dillon	59725	(406) 683-5242

TankID/Alt TankID	Tag	Installed	Product	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																								
Status	Number	Age/AST	Capacity	Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/CP																								
1 / 01 Currently In Use	3995	4/1/1982 24 / No	Other 12,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
2 / 02 Currently In Use	3996	4/1/1982 24 / No	Other 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Bare Steel Impressed Current	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Beaverhead

Owner Name and Address: Safeway Stores Inc 1121 124th Ave NE Bellevue WA 98005 Phone: (425) 455-6545

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613989	Safeway 1581 Dillon	570 N Montana St	Dillon	59725	

TankID/Alt TankID	Tag Number	Installed	Product	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/CP																								
1 / 01 Currently In Use	4222	10/9/2000 05 / No	Gasoline 20,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
2 / 02 Currently In Use	4223	10/1/2000 05 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
3 / 03 Currently In Use	4224	10/1/2000 05 / No	Diesel 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td></td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
B			<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Beaverhead

Owner Name and Address: Circle S of Montana 30300 Highway 278 Jackson MT 59736 Phone: (406) 834-3497

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0107024	Circle S Ranch	30300 MT Highway 278	Jackson	59736	(406) 834-3497

TankID/Alt TankID	Tag	Installed	Product	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																								
Status	Number	Age/AST	Capacity	Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/CP																								
5 / 05 Currently In Use	4228	7/1/1997 09 / No	Diesel 1,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L		B		D	E	F	<input checked="" type="radio"/>	H	I	<input checked="" type="radio"/>	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
	B		D	E	F	<input checked="" type="radio"/>	H	I	<input checked="" type="radio"/>	K	L																					
6 / 06 Currently In Use	4229	7/1/1997 09 / No	Gasoline 1,000	Polyethylene Tank Jacket Double-Walled	Flexible Plastic Double-Walled	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td></td><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L		B		D	E	F	<input checked="" type="radio"/>	H	I	<input checked="" type="radio"/>	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
	B		D	E	F	<input checked="" type="radio"/>	H	I	<input checked="" type="radio"/>	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Beaverhead

Owner Name and Address: Kevin Stosich PO Box 206 Lima MT 59739 Phone: (406) 276-3431

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0100671	Ralphs Exxon	114 N Harrison Ave	Lima	59739	(406) 276-3431

TankID/Alt TankID	Tag	Installed	Product	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																								
Status	Number	Age/AST	Capacity	Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/CP																								
7 / 07 Currently In Use	2078	9/1/1998 07 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					
8 / 08 Currently In Use	2079	9/1/1998 07 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B		D		E	F	<input checked="" type="radio"/>	H	I	J	K	L																					

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Beaverhead

Owner Name and Address: Lima School Dist 12 Inc PO Box 186 Lima MT 59739 Phone: (406) 276-3571

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0107158	Lima School Dist 12 Inc	1 N Harrison St	Lima	59739	(406) 276-3571

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
3 / 03 Currently in Use	1535	6/1/1992 14 / No	Diesel 10,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Beaverhead

Owner Name and Address: Ed Stede PO Box 175 Wisdom MT 59761 Phone: (406) 689-3225

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0102173	Big Hole Petroleum Inc	MT Highway 43 PO Box 175	Wisdom	59761	(406) 689-3225

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction	Piping Material		Tank Release Detection	FR Met																						
Status				Secondary Option	Secondary Option	Piping Type	Piping Release Detection	Spill/Overl/CP																						
1 / 01 Currently in Use	3323	3/10/1985 21 / No	Gasoline 2,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	U.S. Suction	<table><tr><td>A</td><td><input checked="" type="radio"/></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	<input checked="" type="radio"/>	D	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>		D	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	<input checked="" type="radio"/>	D	E	F	G	H	I	J	K	L																				
<input checked="" type="radio"/>		D	E	F	G	H	I	J	K	L																				
2 / 02 Currently in Use	3324	3/10/1985 21 / No	Gasoline 1,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	U.S. Suction	<table><tr><td>A</td><td><input checked="" type="radio"/></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	<input checked="" type="radio"/>	D	E	F	G	H	I	J	K	L	<input checked="" type="radio"/>		D	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	<input checked="" type="radio"/>	D	E	F	G	H	I	J	K	L																				
<input checked="" type="radio"/>		D	E	F	G	H	I	J	K	L																				

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Summary of Facility Information in the County of Beaverhead

Owner Name and Address: Ron Wilkinson PO Box 159 Wise River MT 59762 Phone: (406) 832-3271

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
0102080	Wise River Store	MT Highway 43	Wise River	59762	(406) 832-3271

TankID/Alt TankID	Tag Number	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection	Piping Release Detection	FR Met
3 / 03 Currently In Use	1224	6/1/1998 08 / No	Gasoline 2,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed